

|                                                                                                                                                                                                        |                                              |                                     |          |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|-------------------------------------|----------|
| 2019 BMW X7 xDrive 35d Design<br>Pure Excellence                                                                                                                                                       |                                              | OVERALL                             |          |
|                                                                                                                                                                                                        |                                              | 4.5                                 |          |
|                                                                                                                                                                                                        |                                              | EXTERIOR                            | INTERIOR |
|                                                                                                                                                                                                        |                                              | -                                   | -        |
| MODEL CODE<br>3DA-CW30                                                                                                                                                                                 | DISPLACEMENT<br>2,992 cc                     |                                     |          |
| YEAR / REG.<br>2019/09                                                                                                                                                                                 | MILEAGE<br>66,407 km                         |                                     |          |
| DOORS<br>5                                                                                                                                                                                             | SEATS<br>6                                   |                                     |          |
| DRIVETRAIN<br>4WD                                                                                                                                                                                      | TRANSMISSION<br>AT                           |                                     |          |
| FUEL<br>Diesel                                                                                                                                                                                         | STEERING<br>Right                            |                                     |          |
| EXTERIOR COLOR<br>Gray                                                                                                                                                                                 | BODY TYPE<br>SUV                             |                                     |          |
| CHASSIS NO.<br>WBACW82000LS78349                                                                                                                                                                       | DIMENSIONS (L X W X H)<br>517 × 200 × 184 cm |                                     |          |
| SALES POINTS                                                                                                                                                                                           |                                              |                                     |          |
| Alloy Wheels                                                                                                                                                                                           |                                              | Sunroof                             |          |
| Roof Rails                                                                                                                                                                                             |                                              | Glass Roof                          |          |
| Leather Seats                                                                                                                                                                                          |                                              | Power Tailgate                      |          |
| Power Seats (Front)                                                                                                                                                                                    |                                              | Pre-Collision Braking               |          |
| Adaptive Cruise Control                                                                                                                                                                                |                                              | Parking Assist (Auto Steering)      |          |
| Front Camera                                                                                                                                                                                           |                                              | Side Camera                         |          |
| Back Camera                                                                                                                                                                                            |                                              | 360° Camera                         |          |
| Navigation System                                                                                                                                                                                      |                                              | harman/kardon Surround Sound System |          |
| Rear Seat Entertainment (Rear Seat Ent...                                                                                                                                                              |                                              |                                     |          |
| INSPECTOR REPORT                                                                                                                                                                                       |                                              |                                     |          |
| Exterior: Minor scratches and dents have been repaired, but small scratches and dents remain.<br>Interior: Some noticeable stains are present in parts. Repair history: No abnormalities in the frame. |                                              |                                     |          |

[illegible]