

2019 BMW BMW2seriesGranTourer 218i Gran Tourer Luxury		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
6V15	1,498 cc		
YEAR / REG.	MILEAGE		
2019/11	57,400 km		
DOORS	SEATS		
5	7		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WBA6V720905P04988	459 × 180 × 164 cm		
SALES POINTS			
Alloy Wheels		Leather Seats (Perforated Dakota Leath...	
Power Seats (Front)		Pre-Collision Braking	
Parking Assist (Auto Steering)		Back Camera	
Navigation System			
INSPECTOR REPORT			
Moldings are dull. Wheels have scratches and scrapes. Exterior: Minor scratches and dents have been repaired, but some small scratches and dents remain. Interior: Some noticeable dirt and stains are present. No abnormalities in the frame/structural components.			

[illegible]