


2019 BMW_Mini BMW Mini 3HB Cooper		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-XR15M	1,498 cc		
YEAR / REG.	MILEAGE		
2019/11	16,240 km		
DOORS	SEATS		
3	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WMWXR320202L85923	384 × 173 × 143 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Cruise Control		Navigation System	
INSPECTOR REPORT			
Light interior stains, top sticker cracked			

初年度登録		ドア数		ボディ形状		年価点	
R1 / 11月		MINI		3		コンパクトハッチバック	
車名		MINI		グレード		駆動方式 4WD	
		クーバー				4	
車種 良型用・その他()		排気量 1500 CC		型式 DBA-XR15M		通称 A・B・C	
車検 - - 年 / 月 ()		燃料 ガソリン		ディーゼル		後日送り品 ()	
走行 口内マーク付輸入車() + 万 千 百 十 円 1 6 , 2 4 0 マイル		シフト ハイブリッド ()		AT		税目区分 ()	
外装色 ホワイト ()		カラーNo. AG・WG・WAG・()		エンジン AG・WG・WAG・()		装備品のみの印を記入	
()		内装色 標準定員 4人		安全装置 Fg Fw AM サンルーフ革シート		キーレス	
パネール左・右・前・後・デモ・走行		16,240円 + 預託金		エレクトロニクス		TV	
セールスポイント							
★カメラ&パーキングアシストパッケージ★ジャベッパ パッケージ★オプション15インチアルミ★純正ナビ★ バックカメラ★前後PDC★コンフォートアクセス ★ETC★クロームラインエクステリア★ドライビングア シスト★パークアシスト★アームレスト★前後ドライブ レコーダー★スペーキー							
検査記入欄							
ルーム内薄汚れ 上面ステッカーワレ							
修理履歴 有 ()							
A	型式	U	ヘコみヤレ	B	ガラスへコみ	P	熱変色・ボロボロ
W	経年劣化	S	サビ	C	腐食	X	交換済
登録地	月 日						まで各店である
車体番号	WMWXR320202L85923						
FW	()	備A	フレ	外装	小	ホイール	エアロ
内装	ヨゴレ	シミ	ヤブレ	コゲ	コガレ	オーディオ	シリアル
							No.
							最大積載量



A	キズ	U	ヘルメツオサレ	B	キズ+ヘルメツ	P	色あせ+ボケ	G	ガラスキズ
W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換済
									名義人
登録No.								月 日 までに名義である	
車体番号		WMWXR320202185923							
シリアルNo.									
車種	乗込	種		高さ		最大積重量			