

2019 BMW_Mini BMW Mini 5HB Cooper D		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-XT15M	DISPLACEMENT 1,496 cc		
YEAR / REG. 2019/10	MILEAGE 43,018 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Hatchback		
CHASSIS NO. WMWXT320902L23890	DIMENSIONS (L X W X H) 400 × 173 × 145 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Navigation System			
INSPECTOR REPORT			
Door trim scratches, interior trim scratches, steering wheel scratches, missing antenna.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 / 10月	メーカー MINI MINI	ドア枚数 5	ボディ形状 コンパクトハッチバック	評価値 4.5					
車種 自家用・その他 ()	排気量 1500 CC	型式 LDA-XT15M	駆動区分 2WD 4WD	内装 A・B・D					
車検 - 年 - 月 / 日	燃料 ガソリン ハイブリッド ()	変速機 AT	後付選り品 (保証書・取扱説明書 等)						
走行 43,018 km	シフト AT	エアコン	装備品のみ O印 を記入						
外装色 シロ / クロ	カラーNo. ()	AG・AG・WAG・()	装備品のみ O印 を記入						
内装色 ()	乗車定員 5 人	リサイクル料	サンルーフ	革シート					
左・前・後 左・前・後	走行 17,600円	預託料	エブリック	TV					
セールスポイント									
バックモニター									
特記事項									
16インチアルミホイール									
検査記入欄									
ドア内張傷、室内内張傷、ハンドル傷、アンテナ欠品									
修理歴									
有・無									
A	キズ	U	ヘビイオサレ	B	キズ・ヘビイ	P	色あせ・ボケ	G	ガラスキズ
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
登録No.					名義中				
月 日					家での名義である方				
車体番号					WMWXT320902L23890				
シリアルNo.									
FW	トビ	傷A	ワレ	外装	小	ホイール	エアロ		
内装	シロ	ヤブレ	コガ	コガ穴	オーディオ	CD	ナビ	最大積載量	Kg