

2019 BMW_Mini BMW Mini 5HB Cooper S		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-XU20M	1,998 cc		
YEAR / REG.	MILEAGE		
2019/08	20,659 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WMWXU920802L18129	402 × 173 × 145 cm		
SALES POINTS			
Alloy Wheels		Leather Seats	
Pre-Collision Braking		Adaptive Cruise Control	
Back Camera		Navigation System	
INSPECTOR REPORT			
Minor wear on steering, seats, trim, and headliner. Minor exterior paint thinness and door mirror damage. Stone chip on power window. Interior dirt and a hole from a removed audio unit.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録番号 R1/8月	メーカー MINI	ドア数 5	ボディ形状 コンパクト/ハッチバック	評価点 4.5
車名 MINI	グレード クーパーS	駆動方式 4WD	燃費区分 4WD	
車種 自家用・その他()	排気量 1990 cc	型式 DBA-XU20M	通称 A・B・C	内装 A・B・C
車検 8年8月	燃料 ガソリン	ディーゼル	後付部品 ()	
走行 20,659 km	シフト AT			
外装色 レッド (851)	カラーNo. (851)	エアコン	後付部品のみ O印 を記入	
内装色 その他	乗車定員 5人	PS	サンルーフ	キーレス
走行距離 17,600 km	リサイクル料	エアロ	ABS	ナビ
セールスポイント クルーズコントロール ハンズフリー ブラックアウトカスタム				
検査記入欄 ステアリングスレ シートスレ トリムA 天幕スレ 外装傷A ドアミラーA	修復歴 有・無			
	A キズ B 凹み C 穴 D 腐食 E 変色 F 変形 G 変質 H 変質 I 変質 J 変質 K 変質 L 変質 M 変質 N 変質 O 変質 P 変質 Q 変質 R 変質 S 変質 T 変質 U 変質 V 変質 W 変質 X 変質 Y 変質 Z 変質			
	名義中 月 日 までには名義できる方			
	車検 WMWXU920802L18129			
	重量 0 kg			