

2019 BMW_Mini BMW Mini 5HB Cooper S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE XU20M	DISPLACEMENT 1,998 cc		
YEAR / REG. 2019/06	MILEAGE 19,359 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Hatchback		
CHASSIS NO. WMWXU92050TX52325	DIMENSIONS (L X W X H) 402 × 173 × 145 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Navigation System		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Exterior: Major scratches and dents have been repaired, but minor ones remain. Interior: Some noticeable stains are present. No frame damage.			

ORIGINAL JAPANESE AUCTION SHEET

青森県内のカー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 R1/6月	メーカー MINI	ドアク数 5	ボディ形状 コンパクトハッチバック	評価点 4
車種 MINI	グレード クーパース	年式 2000	燃料 ガソリン	内装 B
用途 自家用	ディーラー 右	車体色 XU20M	駆動方式 2000	エンジン AC
年式 19年	月 3月	日 19日	走行距離 19,359 km	電圧 12V
外装色 チリレッド/白	カラーNo. ()	リサイクル料 16,240円	販売番号 WMWXU92050TX52325	重量 Kg
シフト フロア 7 AT	乗車定員 5人	長さ cm	幅 cm	高さ cm

車検返却日
()

整備
()

セールスポイント
()

バックカメラ/TC/横滑り防止装置 (E S C) / 運転席エアバック/後部座席防止システム/スマートキー/キーレスエントリー/A B S / 助手席エアバック/サイドエアバック/H D / ナビ/衝突被害軽減ブレーキ/ガイドリン/グリップ/ターボ/オートマン/ミュージック/サーボ/ミュージックプレーヤー/後部可
査定員記入欄
()

※ダメージレベルに関する注意事項
()

クオリティグレード説明
()

外装: 劣化する平ズやヘコミは補修済みですが、小さな平ズやヘコミが残っています。
内装: 劣化する汚れ等が、部分的にあります。
修理歴: 骨格部位に異常はありません。

車検返却日: 停止状態で実施できる範囲で行います。