

2019 BMW_Mini BMW Mini Clubman Cooper Clubman		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LV15M	DISPLACEMENT 1,498 cc		
YEAR / REG. 2019/11	MILEAGE 20,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Station Wagon		
CHASSIS NO. WMWLV320802L88075	DIMENSIONS (L X W X H) 428 × 180 × 147 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Navigation System		Pre-Collision Braking Back Camera	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 / 11月	メーカー MINI	ドア枚数 5	ボディ形状 ステーションワゴン	評価点 4.5
車名 MINI	グレード クーパー クラブマン AIS検査済	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 1500 CC	型式 LV15M	選装 型式	内装 A・B・C
車検 8年11月	抹消 燃料 ハイブリッド ()	ディーゼル シフト マイル	最良選用品 (保証書・取扱説明書等)	
走行 20,000 km	フロア 7 AT	保証書・記録簿・取説・スペアキー		
外装色 エニグマティックブラック	カラーNo. ()	エアコン Qd・AAG・WAG ()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5人	安全色 ()	サンルーフ	革シート
左・右 左・右	輸入 ディーラー	走行 17,800 km	エレクトロニクス TV	その他 TV
セールスポイント				
バックカメラ/横滑り防止装置 (ESC) /運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/サイドエアバック/H D Dナビ/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/ターボ/シートヒーター/ミュージックサーバー/ミュージックプレーヤー接続可				
検査記入欄				
A キズ U ヘッドライト B キズ・ヘッパ P 色あせ・ボケ Q ガラスキズ W 補修跡 S ヤビ C 腐食 X 交換済 YX 交換済 登録No. 月 日 までに名義である方 車体番号 WMWLV320802L88075 FW トボ石 傷A フレ 外装 小 A・曲 A・フレ 内装 ヨゴレ シシ ヤブレ コガ コガ穴 オーディオA				