

2019 BMW_Mini BMW Mini Crossover Cooper D		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-YT20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2019/03	MILEAGE 24,000 km		
DOORS 5	SEATS 5		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Blue		
BODY TYPE SUV			
CHASSIS NO. WMWYT920093F83436	DIMENSIONS (L X W X H) 432 × 182 × 160 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Back Camera		Roof Rails Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H31/3月	メーカー MINI	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 4.5
車名 MINI	グレード クーバー D	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 2000 CC	型式 LDA-YT20	選定 型式	内装 ①・B・C
車検 - 年 - 月 / ①	燃料 ガソリン ハイブリッド ()	タイプ ①	後日送付品 (① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿)	
走行 24,000 km	シフト フロア 8 AT	保証書・取説・スペアキー後日送付		
外装色 ラピスラジュアリーブルー	カラーNo. ()	エアコン ①・AAG・WAG・()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5 人	PS	PW	AW
左・右 左・右	タイヤ ①	エアバック	ABS	ナビ
19,090 円	販売税	エアバック	ABS	ナビ
セールスポイント シートカバー白・FRドラレコ・バックカメラ・シートヒーター・Bluetooth・ナビ・USB・AUX・ラジオ・スマートキー・オートライト・パワートランク・衝突軽減ブレーキ・追従クルコン		修復歴 有 ①		
特記事項 AISカーセンサー認定済み 4.5点 スペアキー有り		A キズ U ヘッドライト B キズヘッド P 色あせ・ボケ Q ガラスキズ W 補修跡 S ヤビ C 腐食 X 交換済 YX 交換済		
検査記入欄		登録月 年 日 名義中 車体番号 WMWYT920093F83436		
FW トビ石 傷A フレ 小 A・U ① ホイル A・フレ	シリアル No.			
内装 ヨゴレ シシ ヤブレ コガ コガ穴 オーディオ穴 ①	長さ cm	幅 cm	高さ cm	最大積載量 Kg