

2019 BMW_Mini BMW Mini Crossover Cooper D Crossover		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE YT20	DISPLACEMENT 1,995 cc		
YEAR / REG. 2019/03	MILEAGE 40,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE SUV		
CHASSIS NO. WMWYT920203F83004	DIMENSIONS (L X W X H) 432 × 182 × 160 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Back Camera		Roof Rails Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H31/3月	メーカー MINI	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 4.5
車名 MINI	グレード クーパーD クロス オーバー AIS検査済	駆動区分 2WD 4WD		
車種 自家用・その他()	排気量 2000 CC	型式 YT20	選装 型式	内装 A・B・C
車検 8年8月	抹消 燃料 ガソリン ハイブリッド	シフト マイル	最良選用品(保証書・取扱説明書等)	
走行 40,000 km	フロア 8 AT	取扱説明書・記録簿・スペアキー		
外装色 アイランドブルー	カラーNo. ()	エアコン QW・AAG・WAG・()	装備品のみのO印を記入	
内装色 ()	乗車定員 5人	サンルーフ A1	革シート A1	
左・右 左・右	輸入 区分	走行 19,090 km	エレクトロニクス A1	TV A1
セールスポイント				
バックカメラ/横滑り防止装置(ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/サイドエアバック/H D Dナビ/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/ターボ/電動リアゲート/ミュージックサーバー/ミュージックプレーヤー接続可				
検査記入欄				
A キズ U ヘッドライト B キズ・ヘッパ P 色あせ・ボケ Q ガラスキズ W 燃費計 S ヤビ C 腐食 X 交換済 YX 交換済				
登録No. 月 日 までに名義である方				
車体番号 WMWYT920203F83004				
FW トボ石 傷A フレ 外装 小 A・曲 A・フレ エアロ シリアル No.				
内装 ヨゴレ シシ ヤブレ コガ コガ穴 オーディオA 取組 長さ cm 幅 cm 高さ cm 最大積載量 Kg				