

2019 BMW_Mini BMW Mini Crossover Cooper S		OVERALL 4.5	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-YS20	DISPLACEMENT 1,998 cc		
YEAR / REG. 2019/03	MILEAGE 21,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE SUV		
CHASSIS NO. WMWYS920X03G51715	DIMENSIONS (L X W X H) 431 × 182 × 159 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Adaptive Cruise Control Navigation System		Roof Rails Pre-Collision Braking Back Camera	
INSPECTOR REPORT			
Small wrinkles on seats, minor wear on door trim, minor exterior scratches.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H31/3月	メーカー MINI	ドア数 5	ボディ形状 SUV/クロカン	評価点 4.5
車名 MINI	グレード クーパーS	駆動方式 2WD	燃費区分 4WD	
車種 自家用・その他()	排気量 2000 cc	型式 DBA-YS20	国産 A・⑨・C	
登録 - 年 - 月 - 日	燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書等)	
走行 21,000 km	フロア 8 AT			
外装色 ブルー	カラーNo.	エンジン G0・AAG・WAG・()	装備品のみ・C印を記入	
内装色 ()	乗車定員 5人	安全装置 ABS・ESP・VSC・()	サンルーフ	車シート
走行 左・()	走行 19,090 km	価格 19,090円	エレクトロニクス	TV
セールスポイント				
キーレスエントリー/A B S /運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/H D D ナビ/衝突被害軽減ブレーキ/ETC/アイドリングストップ/スマートキー/盗難防止システム/オートクルーズコントロール/L E Dヘッドライト/横滑り防止装置 (ESC) /電動リアゲート/ミュージックプレイヤー接続可/バックカメラ/障害物センサー/M Tモード付き				
検査記入欄				
シートしわ<小> ドア内張りA<小> 外装小傷有				
修復歴 有・⑥				
A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損				
名義中 月 日 まで名義中				
WMWYS920X03G51715				
寸法 全長 431 cm 全幅 182 cm 全高 159 cm 最大積載量 kg				