


2019 Daihatsu Move Canbus GLTDSA3		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 5BA-LA800S	DISPLACEMENT 658 cc		
YEAR / REG. 2019/12	MILEAGE 50,236 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Other		
CHASSIS NO. LA800S-0209311	DIMENSIONS (L X W X H) 340 × 148 × 166 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Both... 360° Camera		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
Minor scratches and dents, wheel chrome plating scratches, some undercarriage rust, seat dents and stains.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		型式番号		車種記号		シリアル番号		評価点		
年	月	日	車名	ドア数	グレード	駆動	4.5			
R 01	12		ムーヴキャンバス	5	Gマイクアップ LTD SA3	4WD				
型式	5BA-LA800S	排気量	660 cc	燃料	ガソリン	軽油	国産	A	C	
車種	R 08	年	12	月	車種	自家用	シフト	CVT	冷暖	AC
走行距離	5	0	2	3	6	km	〇をつける	※	※	
外装色	元色	ベージュ/パール	色替	無	カラーNo.	内装	純正ナビ	純正TV	純正ナビ	純正TV
車台No.	LA800S-0209311	登録No.	滋賀	587	を	1201	リサイクル	8,790	円	未納税
定員	4	人	構造	軽	長さ	cm	幅	cm	高さ	cm
輸入車のみ	モデル	型式	輸入区分	ディーラー	並行	ハンドル	左	〇	新車保証書	車載取扱
セールスポイント 社外メモリーナビ・Bluetooth付いてます♪										
注意事項・不具合箇所										
検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入 小キズ小凹 ホイールCPキズ 下廻り一部サビ シート凹み、シミ										
										
ドアミラー 上角										
キズ										
ヒビ										
シヤッキ										
フレ										