

|                                                                                                                                                                                                    |                                              |                                  |          |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|----------------------------------|----------|
| 2019 Daihatsu Tanto X                                                                                                                                                                              |                                              | OVERALL                          |          |
|                                                                                                                                                                                                    |                                              | 4                                |          |
|                                                                                                                                                                                                    |                                              | EXTERIOR                         | INTERIOR |
|                                                                                                                                                                                                    |                                              | -                                | -        |
| MODEL CODE<br>LA650S                                                                                                                                                                               | DISPLACEMENT<br>658 cc                       |                                  |          |
| YEAR / REG.<br>2019/10                                                                                                                                                                             | MILEAGE<br>133,873 km                        |                                  |          |
| DOORS<br>5                                                                                                                                                                                         | SEATS<br>4                                   |                                  |          |
| DRIVETRAIN<br>2WD (FF)                                                                                                                                                                             | TRANSMISSION<br>AT                           |                                  |          |
| FUEL<br>Petrol                                                                                                                                                                                     | STEERING<br>Right                            |                                  |          |
| EXTERIOR COLOR<br>Pink                                                                                                                                                                             | BODY TYPE<br>Kei                             |                                  |          |
| CHASSIS NO.<br>LA650S-0047119                                                                                                                                                                      | DIMENSIONS (L X W X H)<br>340 × 148 × 178 cm |                                  |          |
| SALES POINTS                                                                                                                                                                                       |                                              |                                  |          |
| Pre-Collision Braking<br>360° Camera                                                                                                                                                               |                                              | Back Camera<br>Navigation System |          |
| INSPECTOR REPORT                                                                                                                                                                                   |                                              |                                  |          |
| Exterior: Noticeable scratches and dents have been repaired, but minor scratches and dents remain.<br>Interior: Some noticeable stains are present. Repair history: No abnormalities in the frame. |                                              |                                  |          |

[illegible]