

|                                                                                                                                                                        |                        |                                        |          |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|----------------------------------------|----------|
| 2019 ES ES300h "F SPORT"                                                                                                                                               |                        | OVERALL                                |          |
|                                                                                                                                                                        |                        | 4                                      |          |
|                                                                                                                                                                        |                        | EXTERIOR                               | INTERIOR |
|                                                                                                                                                                        |                        | -                                      | -        |
| MODEL CODE                                                                                                                                                             | DISPLACEMENT           |                                        |          |
| 6AA-AXZH10                                                                                                                                                             | 2,487 cc               |                                        |          |
| YEAR / REG.                                                                                                                                                            | MILEAGE                |                                        |          |
| 2019/03                                                                                                                                                                | 63,000 km              |                                        |          |
| DOORS                                                                                                                                                                  | SEATS                  |                                        |          |
| 4                                                                                                                                                                      | 5                      |                                        |          |
| DRIVETRAIN                                                                                                                                                             | TRANSMISSION           |                                        |          |
| 2WD (FF)                                                                                                                                                               | AT                     |                                        |          |
| FUEL                                                                                                                                                                   | STEERING               |                                        |          |
| Hybrid (Petrol)                                                                                                                                                        | Right                  |                                        |          |
| EXTERIOR COLOR                                                                                                                                                         | BODY TYPE              |                                        |          |
| Other                                                                                                                                                                  | Sedan                  |                                        |          |
| CHASSIS NO.                                                                                                                                                            | DIMENSIONS (L X W X H) |                                        |          |
| AXZH10-1004057                                                                                                                                                         | 498 × 187 × 145 cm     |                                        |          |
| SALES POINTS                                                                                                                                                           |                        |                                        |          |
| Alloy Wheels                                                                                                                                                           |                        | Sunroof                                |          |
| Leather Seats                                                                                                                                                          |                        | Adaptive Cruise Control                |          |
| Navigation System                                                                                                                                                      |                        | Lexus ES Premium Sound System (8 Sp... |          |
| INSPECTOR REPORT                                                                                                                                                       |                        |                                        |          |
| Exterior: Major scratches and dents have been repaired, but minor ones remain. Interior: Some dirt is present in parts. Repair history: No abnormalities in the frame. |                        |                                        |          |

[illegible]