

2019 HONDA CR-V EX Masterpiece		OVERALL 4	
		EXTERIOR C	INTERIOR C
MODEL CODE DBA-RW1	DISPLACEMENT 1,496 cc		
YEAR / REG. 2019/06	MANUFACTURE YEAR 2019		
MILEAGE 64,167 km	DOORS 5		
SEATS 5	DRIVETRAIN 2WD (FF)		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Dark Blue		
INTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. RW1-1005286	DIMENSIONS (L X W X H) 461 × 186 × 168 cm		
SALES POINTS			
Alloy Wheels Sunroof Exterior Parts Power Tailgate		Leather Seats (Leather) Adaptive Cruise Control Navigation System (SSD Navigation)	
INSPECTOR REPORT			
Adhesive residue on exterior, scratches on steering wheel, scratches on interior trim, minor seat wear, interior dirty with animal hair.			

ORIGINAL JAPANESE AUCTION SHEET

出品番号 52052	初度登録 R 1 年 6月	車名 CR-V	ドア形状 5W	グレード EX・マスターピース	評価点 4				
		車種 自家用	排気量 1500 cc	燃料 ガソリン	型式 DBA-RW1				
走行 64,167 km	年 月	登録番号	譲渡登録期日	セールスポイント					
シフト エアコン	外装色 コン	乗車定員 5人	最大積載量 kg	★オークションデビュー★ ホンダセンシング パワーテールゲート 前席シートヒーター					
IAT AAC	カラーNo. B610M	内装色 クロ	輸入車 リサイクル車						
保証書	後日発送部品		11,160円						
注意事項 18インチAW VXM-197VFNI バックモニター			同正装備 18" TV SR 17" ABS 17B 7速 PS PW						
検査員記入欄			車台番号 RW1-1005286						
外装のり付 ハンドル傷 室内内張傷 シートすれ小 室内汚れ、動物の毛			長さ 幅 高さ						
			車台番号 RW1-1005286						
事務用よりご案内 ◆新港ヤード◆千葉県千葉市美浜区新港227-13									

A:外 B:内 C:12 P:要確認 N:補修部 S:損 C:腐食 G:7200h*93点検 XX:交換済み X:要交換 内:外装野底 S:総検分付点(A+B+C+D+E) 1