

2019 Honda Insight EX		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE ZE4	DISPLACEMENT 1,496 cc		
YEAR / REG. 2019/10	MILEAGE 24,421 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Sedan		
CHASSIS NO. ZE4-1008847	DIMENSIONS (L X W X H) 468 × 182 × 141 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Back Camera		Power Seats (Front) Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Minor scratches on mirror, pillar trim, and bottom of front bumper. Minor scuffs on seat and steering wheel. Scrape on front under cover.			

初年度登録		メーカー ホンダ		ドア数 4		ボディ形状 セダン		評価点 4.5																															
R1 10月		車名 インサイト		グレード E X		燃費区分 2WD 4WD																																	
車種 自家用・その他()		排気量 1500 CC		型式 ZE4		通称 型式		内装 A・G・C																															
年次 8年10月		扶消 燃料ガソリン 変換ハッチバック		ディーゼル		養護等品目(保証書・取扱説明書等)																																	
走行 コロンマークを記入(A・位置・色・数字・印・文字) 24,421マイル		シフト フロア AT		新製品のみのO印を記入																																			
外装色 シルバー		カラーNo. QD・AAD・WAG・()																																					
()		内装色 黒色		乗員定員 5人		安全装備																																	
左・右 輸入区分		ディーター・車行		リサイクル車		エレクトロニクス																																	
		10,760円		買付額		エレクトロニクス																																	
セールスポイント																																							
オートハイビーム、レーンアシスト、レーザークルーズ、助手席エアバック、サイドエアバッグ、ESC、MTモード付き、フルフラットシート、Bカメラ、ETC																																							
検査記入欄																																							
ミラーA(小)、シートずれ(小)、ピラー内張りA(小)、ハンドルずれ(小)、フロントアンダーカバーすり、Fバンパー下面A有																																							
修復歴 有。(●)																																							
<table border="1"> <thead> <tr> <th>W</th> <th>キズ</th> <th>U</th> <th>ヒコケサレ</th> <th>H</th> <th>キズヘコ</th> <th>P</th> <th>色あせ・汚れ</th> <th>G</th> <th>ガラスキズ</th> </tr> <tr> <th>腐蝕部</th> <th>S</th> <th>ヤレ</th> <th>C</th> <th>腐食</th> <th>X</th> <th>交換済</th> <th></th> <th></th> <th>交換済</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table> 査察No. _____ 月 _____ 日 _____ 年 氏名 _____ 車体番号 ZE-4-1008847										W	キズ	U	ヒコケサレ	H	キズヘコ	P	色あせ・汚れ	G	ガラスキズ	腐蝕部	S	ヤレ	C	腐食	X	交換済			交換済										
W	キズ	U	ヒコケサレ	H	キズヘコ	P	色あせ・汚れ	G	ガラスキズ																														
腐蝕部	S	ヤレ	C	腐食	X	交換済			交換済																														
<table border="1"> <thead> <tr> <th>FW</th> <th>(●)</th> <th>傷A</th> <th>フレ</th> <th>内装</th> <th>ホ</th> <th>ホイール</th> <th>エアロ</th> <th>シリアル</th> <th>製造</th> </tr> <tr> <th></th> <th>(●)</th> <th>(●)</th> <th>(●)</th> <th>(●)</th> <th>(●)</th> <th>(●)</th> <th>(●)</th> <th>(●)</th> <th>(●)</th> </tr> </thead> <tbody> <tr> <td>内装</td> <td>(●)</td> <td>シボ</td> <td>ヤレ</td> <td>コグス</td> <td>オチ・バサ</td> <td>(●)</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>										FW	(●)	傷A	フレ	内装	ホ	ホイール	エアロ	シリアル	製造		(●)	(●)	(●)	(●)	(●)	(●)	(●)	(●)	(●)	内装	(●)	シボ	ヤレ	コグス	オチ・バサ	(●)			
FW	(●)	傷A	フレ	内装	ホ	ホイール	エアロ	シリアル	製造																														
	(●)	(●)	(●)	(●)	(●)	(●)	(●)	(●)	(●)																														
内装	(●)	シボ	ヤレ	コグス	オチ・バサ	(●)																																	