

2019 Honda N BOX Custom GL Honda Sensing		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
JF3	658 cc		
YEAR / REG.	MILEAGE		
2019/06	47,323 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF3-1265597	340 × 148 × 179 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Navigation System			
INSPECTOR REPORT			
Headliner slight scuff, seat slight sag, seat slight scuff, door trim A (medium), TR repair marks, headlight lens deterioration.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 R1 / 6月	メーカー ホンダ	ドア枚数 5	ボディ形状 軽四	評価点 4
車名 N-BOXカスタム	グレード G・Lホンダセンシング	駆動区分 2WD	4WD	
車種 自家用・その他 ()	排気量 660 cc	型式 JF3	燃費 型式	内装 A・B・C
車検 - 年 - 月 / 日	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書等)	
走行 47,323 km	インパネ	AT		
外装色 クリスタルブラックパール	カラーNo.	エアコン	新着品のみ O印 を記入	
()	色車検はO印を 「色検」に記入	4人	サンルーフ	高シート
小 左・右	輸入 区分	ディーラー	走行	8,110円・税込
セールポイント				
CD/バックカメラ/ESC/横滑り防止装置 (ESC)/運転 席エアバック/スマートキー/キーレスエントリー/ABS/ 助手席エアバック/メモリーナビ他/ワンセグTV/衝突被 害軽減ブレーキ/アイドリングストップ/オートクルーズ コントロール/ベンチシート/DVD再生				
検査記入欄				
天板りすれ<小> シートへたり<小> シートすれ<小> ドア内張りA<中> TR修理跡 ヘッドライトレンズ劣化				
修復歴 有・無				
A キズ U ヘコみ/サレ B キズ/ヘコみ P 色あせ/汚れ Q ガラスズレ W 腐蝕跡 S サビ C 露出 X 交換品 XX 交換済				
名義中				
月 日 までに名義できる方				
車体 番号 JF3-1265597				
シリアル No.				
FW トンネル フレ 外装 小 ホイル エアロ ④・⑤ ④・⑤ A・フレ				
内装 ③④ シミ ヤブレ コゲ コガサ オーディオ穴 ④				
長さ 幅 高さ 最大積載量				
kg				