

2019 Honda N BOX G Honda Sensing		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
JF3	658 cc		
YEAR / REG.	MILEAGE		
2019/07	34,049 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF3-1273002	340 × 148 × 179 cm		
SALES POINTS			
Pre-Collision Braking		Adaptive Cruise Control	
Navigation System			
INSPECTOR REPORT			
Tire cracks, minor exterior scratches, headlight lens deterioration, minor seat scuffs, front undercarriage, wheel cover A			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 R1 / 7月	メーカー ホンダ	ドア枚数 5	ボディ形状 軽四	評価点 4.5
車名 N-BOX	グレード Gホンダセンシン	駆動方式 2WD	4WD	
車種 自家用・その他 ()	排気量 660 cc	型式 JF3	燃費 型式	内装 A・B・C
車検 - 年 - 月 / 日	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書等)	
走行 34,049マイル	インパネ	AT		
外装色 モーニングミストブルーメタリック	カラーNo. Qd・AAG・WAG・()	エアコン	新着品のみ O印 を記入	
内装色 ()	乗車定員 4人	PS	PS	AW
小回り 左・右	輸入 ディーラー・直行	8,110円・税込	エアロック	ABS
セールスポイント				
CD/バックカメラ/ESC/横滑り防止装置 (ESC)/運転席エアバック/スマートキー/キーレスエントリー/助手席エアバック/メモリーナビ他/ワンセグTV/衝突被害軽減ブレーキ/アイドリングストップ/オートクルーズコントロール/ベンチシート				
検査記入欄				
タイヤヒビ 外装小傷有 ヘッドライトレンズ劣化 「シートすれく小」 F通り下廻り ホイールカバー A				
修復歴 有・無				
A キズ U ヘコみ/サレ B キズ/ヘコみ P 色あせ/汚れ Q ガラスズレ W 腐蝕品 S サビ C 腐食 X 交換品 XX 交換済				
登録No. 月 日 までには名義できる方				
車体番号 JF3-1273002				
FW トボ石 傷A フレ 外装 小 ホイル エアロ シリアル A・U A・曲 A・フレ No.				
内装 ミゴレ シミ ヤブレ コガ オーディオ穴 スレ 長さ 幅 高さ 最大積載量				