

2019 Honda N BOX G Honda Sensing		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-JF4	658 cc		
YEAR / REG.	MILEAGE		
2019/03	60,871 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF4-1033181	339 × 147 × 181 cm		
SALES POINTS			
Pre-Collision Braking		Adaptive Cruise Control	
Navigation System			
INSPECTOR REPORT			
Front windshield: stone chips, cracks. Interior: scratches, dirt, scuffs. Door mirror scratches. Wheels protrude. Lower support bent.			

ORIGINAL JAPANESE AUCTION SHEET

出品票

型式番号18657 車両区分番号0001 シリアル番号

年式H 31 3月 車名N BOX 5 D グレードG ホンダセンシング 2WD 3.5

型式DBA-JF4 排気量660 cc 燃料ガソリン 駆動方式前輪駆動

車種軽自動車 用途自家用 シフトAT 変速機AC

走行距離60,871 km 色パール 色替無し カラーNo. 内装色 純正ナビ 純正TV

車台No.JF4-1033181 リサイクル 8,110円 廃止金 未償還 純正AW エアB

登録No.抹消 4人 乗車定員 339 mm 147 mm 181 mm TV機能 (社外品含む) 純正AW エアB

輸入車のみ 輸入区分 ディーラー 並行 ハンドル 左 純正ナビ ナビ機能 (社外品含む) 純正TV

セールスポイント AT・4WD・スマートキー・純正ナビ・バックカメラ・ETC・横滑り防止装置・ブレーキサポート・ステアリングスイッチ・クルーズコントロール・両側スライドドア・社外アルミホイール

注意事項・不具合箇所

検査員記入欄: 修復歴「有」の場合は修復箇所・交換箇所を記入

フロントウィンドー 飛び石、ひび割れ

内装 キズ、汚れ、スレ

ドアミラーキズ

ホイールはみ出し

ロアサポート歪み

ドアミラー 上下 キズ ヒビ フレ

上側 無 シヤッキ 無

図面

U2 A2 A1 U1 U2 A1 A1 S1 U1 U1 U1 U2

7 mm 7 mm 9 mm 9 mm