

2019 Honda N BOX G Honda Sensing		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
JF3	658 cc		
YEAR / REG.	MILEAGE		
2019/07	10,568 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Silver	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF3-1286424	340 × 148 × 179 cm		
SALES POINTS			
Pre-Collision Braking		Adaptive Cruise Control	
Navigation System			
INSPECTOR REPORT			
Whitening on unpainted resin parts, small stone chip on front glass, minor scuffs on wheel covers, minor exterior scratches, headlight haziness.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 R1 / 7月	メーカー ホンダ	ドア枚数 5	ボディ形状 軽四	評価点 4.5
車名 N-BOX	グレード Gホンダセンシン	駆動方式 2WD	4WD	
車種 自家用・その他 ()	排気量 660 cc	型式 JF3	燃費 型式	内装 A・B・C
車検 - - 年 / 月 / 日	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書等)	
走行 10,568 km	インパネ	AT		
外装色 ルナシルパーメタリック	カラーNo. Qd・AAG・WAG・()	エアコン	新着品のみ O印 を記入	
乗人数 4人	ドアロック	AW	サンルーフ	高シート
小・中・大 左・中・右	ディーラー 走行	8,110円・預託金	エレクトロニック	TV
セールスポイント				
フルフラット/バックカメラ/TC機構滑り防止装置 (ESC) /運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/メモリーナビ他/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリッグストップ/オートクルーズコントロール/ベンチシート/両側スライド				
検査記入欄				
無塗装樹脂部白化 F ガラス飛び石<小> ホイールカバー A 外装小傷有 ヘッドライトくもり				
修復歴 有・無				
A キズ U ヘコみ/サビ B キズ/ヘコみ P 色あせ/汚れ Q ガラスキズ W 雨漏り S サビ C 腐食 X 交換済 YX 交換済				
登録No. 月 日 までには名義できる方				
車体番号 JF3-1286424				
FW トボ石 傷A フレ 外装 小 ホイル エアロ シリアル A・U A・曲 A・フレ No.				
内装 コゴレ シミ ヤブレ コガ 窓ガラス オーディオ穴 スレ 車輪 長さ 幅 高さ 最大積載量				