

2019 Honda N BOX G Honda Sensing		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-JF3	658 cc		
YEAR / REG.	MILEAGE		
2019/09	62,000 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF3-1312212	340 × 148 × 179 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Front support XX, right front instrument panel repaired, left rear fender XX, left rear wheel arch outer distortion, steering wheel wear, some interior dirt and scratches, minor scratches.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 R1 / 9月	メーカー ホンダ	ドア枚数 5	駆動方式 軽四	評価点 R
車名 N-BOX	グレード Gホンダセンシン	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 660	型式 DBA-JF3	通称 型式	内装 A・B・C
燃料 ハイブリッド	ディーゼル ()	検定通り品 (保証書・取扱説明書 等)		
走行 62,000 km	インパネ CVT			
外装色 パール	カラーNo. (NH883P)	エアコン AG・AG・WAG・()	装備品のみ O印 を記入	
()	内装色 ()	乗車定員 4人	PS	AW
左・右 左・右	ディーラー ディーラー	走行 8,110 km	エアロ	サンルーフ
セールスポイント ユーザー買取 社外ナビ フルセグ バックカメラ LEDライト スマキー		修復歴 0・無		
検査記入欄 トサボートXX 右フィン/本修正 左RフェンダーXX 左Rタイヤハウスアウターヒズミ ハンドルハゲ ルーム内一部汚れ・キズ 小傷		A キズ U ヘッドライト B キズ・ヘッド C 色あせ・ボケ D ガラスキズ W 補修跡 S サイズ C 腐食 X 交換済 XX 交換済 登録No. 月 日 までに名義できる方 車体 番号 JF3-1312212 シリアル No. 長さ cm 幅 cm 高さ cm 最大積載量 Kg		
内装 ゴロ	シ	ヤブレ	コガ	コガ穴