

2019 Honda N-BOX GL Honda Sensing		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
JF3	658 cc		
YEAR / REG.	MILEAGE		
2019/08	45,837 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JF3-1296953	340 × 148 × 179 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Drive...		Pre-Collision Braking	
Navigation System			
INSPECTOR REPORT			
Mirror scratch, small scratch on door trim, small scratch on pillar trim, wheel cover scratch, small stone chip on front glass.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 R1 / 8月	メーカー ホンダ	ドア枚数 5	ボディ形状 軽四	評価点 4.5
車名 N-BOX	グレード G・Lホンダセンシング	駆動方式 2WD	燃費区分 4WD	
車種 自家用・その他 ()	排気量 660 cc	型式 JF3	選装 型式	内装 A・B・C
車検 - 年 - 月 / 日	燃料 ガソリン	ディーゼル	検日選択品 (保証書・取扱説明書 等)	
走行 45,837 km	シフト インパネ	AT		
外装色 ブリリアントスポートブルーメタリック	カラーNo. ()	エアコン	新着品のみ O印 を記入	
()	乗車定員 4人	AW	サンルーフ	高シート
小 左・右 大 左・右	輸入 ディーラー	走行 8,110 km	エア パック	タイヤ
セールスポイント				
CD/フルフラット/バックカメラ/TC/横滑り防止装置 (ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/メモリーナビ/ワゴンセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/オートクルーズコントロール/ベンチシート/DVD再生/両側電動スライドドア				
検査記入欄				
ミラーA「ドア内張りA<小> ビラー内張りA<小> ホイールカバーA Fガラス飛び石<小>				
修理歴 有・無				
A キズ U ヘコみ/サビ B キズ/ヘコみ P 色あせ/汚れ Q ガラスズレ W 雨腐蝕 S サビ C 腐食 X 交換品 XX 交換済				
登録No. 月 日 まで任意で変更可能				
車体番号 JF3-1296953				
FW トボ石 傷A フレ 外装 小 ホール エアロ A・U A・曲 A・フレ	シリアル No.			
内装 3ゴレ シミ ヤブレ コガレ オーディオ穴 スレ	長さ cm	幅 cm	高さ cm	最大積載量 kg