

2019 Honda N-VAN 660 L Honda SENSING		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HBD-JJ1	DISPLACEMENT 658 cc		
YEAR / REG. 2019/12	MILEAGE 49,400 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Kei		
CHASSIS NO. JJ1-3033192	DIMENSIONS (L X W X H) 340 × 148 × 195 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Minor scratches on interior and exterior, stone chip on front glass, headliner wrinkles/scuffs.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 12月		メーカー ホンダ		ドア枚数 5	ボディ構造 軽四	評価点 4																				
車名 N-VAN		グレード 660 L ホンダセンシング		駆動区分 2WD 4WD																						
車種 自家用・その他 ()	排気量 660 cc	型式 HBD-JJ1	通称 軽四	内装 A・⑨・C																						
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)																							
走行 49,400 km	シフト インパネ	CVT																								
外装色 ホワイト	カラーNo. (NH906)	エアコン	新着品のみ ○印 を記入																							
内装色 ()	乗車定員 4 人	AW	サンルーフ	革シート																						
ハンド 左・右	輸入 区分	ディーラー	走行 7,510 km	エレクト TV	モ ス																					
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エアバック/メモリーナビ他衝突被害軽減ブレーキ/ETC/横滑り防止装置 (E S C) /両側スライド																										
検査記入欄 内外装コキズ F ガラス落石 天張りシワ・スレ			修復歴 有・⑨ <table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコミ/サレ</td><td>B</td><td>キズ/ヘコミ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table> 登録No. 月 日 までに名変できる方 名変中 車検番号 JJ 1-3033192				A	キズ	U	ヘコミ/サレ	B	キズ/ヘコミ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコミ/サレ	B	キズ/ヘコミ	P	色あせ/ボケ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
FW ⑨	備A	ワレ	外装 ⑨・⑩	小 A・曲	エアロ A・ワレ	シリアル No.																				
内装 ヨゴレ	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	最大積載量 Kg																				