

2019 Honda N-VAN G Honda Sensing		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
JJ1	658 cc		
YEAR / REG.	MILEAGE		
2019/05	52,700 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
JJ1-3021511	340 × 148 × 195 cm		
SALES POINTS			
Pre-Collision Braking		Adaptive Cruise Control	
Navigation System			
INSPECTOR REPORT			
Minor exterior scratches and minor dent (U). Minor scratch on left door mirror (A). Headliner scuffs, seat wrinkles, steering wheel scuffs.			

ORIGINAL JAPANESE AUCTION SHEET

年式 R1 / 5月	メーカー ホンダ	ドア枚数 5	ボディ形状 バン	評価点 4
車名 N-VAN	グレード G・ホンダセンシング	駆動方式 2WD	4WD	
車種 自家用・その他 ()	排気量 660 cc	型式 JJ1	通称 型式	内装 A・⑨・C
年 10年	月 6月	抹消 抹消	燃料 ガソリン	ディーゼル
走行 52,700マイル	インパネ	AT	検日選り品 (保証書・取扱説明書等)	
外装色 ホワイト	カラーNo. ()	エアコン	AG・AG・WAG・()	新着品のみ O印 を記入
小 左・⑧	輸入 区分	ディーラー	走行 7,510円・販売額	PS ⑨
セールスポイント		PS ⑨		
横滑り防止装置 (ESC) /運転席エアバック/キーレス エントリー/助手席エアバック/衝突被害軽減ブレーキ/ア イドリングストップ/オートクルーズコントロール/両側 スライド		ABS ナビ		
検査記入欄		TV ⑩		
外装小キズ、小U 左ドアミラー小A 天張スレ シートシワ ハンドルスレ		修復歴 有・⑤		
FW ⑩		A キズ		
内装 ⑩		W 異音		
シシ		U ヘコみ		
ヤブレ		B キズ・ヘコみ		
コガ		P 色あせ・汚れ		
コガ穴		Q ガラスキズ		
オーデイズ		X 交換		
⑩		XX 交換		
車体 番号		JJ1-3021511		
長さ cm		幅 cm		
高さ cm		最大積載量 kg		