


2019 Honda N-VAN G Honda Sensing		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HBD-JJ1	DISPLACEMENT 658 cc		
YEAR / REG. 2019/08	MILEAGE 83,332 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Kei		
CHASSIS NO. JJ1-3024312	DIMENSIONS (L X W X H) 340 × 148 × 195 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
INSPECTOR REPORT			
Seat wear and stains, headliner wear, exterior deposits, outer mirror damage, front windshield stone chip, interior dirt, general stains, tears, burns, burn holes, audio installation hole, and general scuffs.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 / 8月	メーカー ホンダ	ドア枚数 5	ボディ形状 軽四	評価点 4																				
車名 N-VAN	グレード G・ホンダセンシング	駆動方式 2WD 4WD																						
車種 自家用・その他(営業用)	排気量 660 CC	型式 HBD-JJ1	通称 軽四	内装 A・B																				
車検 - 年 / 月	燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書 等)																					
走行 83,332 km	シフト AT																							
外装色 ホワイト	カラーNo. ()	エアコン	装備品のみ O印 を記入																					
()	内装色 ()	安全装置 ABS・AAS・WAG・()																						
左・右 左・右	輸入 ディーラー・並行	7,510円・預託金	エアバック	ナビ																				
セールスポイント																								
検査記入欄		修復歴 有・無																						
前送付は成約後10日前後がかかります。 シートスレ 天板スレ 外装付着物 シートシミ アウターミラーズ		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ割れ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>			A	キズ	U	ヘコみ割れ	B	キズ・ヘコみ	P	色あせ・ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ割れ	B	キズ・ヘコみ	P	色あせ・ボケ	Q	ガラスキズ															
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済															
登録No.		月 日 までにも受ける方																						
車体番号 JJ1-3024312																								
FW	トビ	座	フレ	外装																				
内装	シス	ヤブレ	コガ	コガ穴																				
オーデコ穴	エアロ	シリアル	No.	重量																				
長さ	幅	高さ	最大積載量	Kg																				