


2019 Honda N-VAN G Honda Sensing		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE HBD-JJ1	DISPLACEMENT 658 cc		
YEAR / REG. 2019/08	MILEAGE 128,432 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Kei		
CHASSIS NO. JJ1-3024313	DIMENSIONS (L X W X H) 340 × 148 × 195 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
INSPECTOR REPORT			
Headliner scuffs, seat stains/scuffs, outer mirror damage.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 8月	メーカー ホンダ 車名 N-VAN	ドア枚数 5 ボディ形状 軽四	評価点 4																				
車種 自家用・その他(営業用)	排気量 660 cc	型式 HBD-JJ1	内装 A・B・C																				
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	後日送付品(保証書・取扱説明書等)																				
走行 128,432 km	シフト AT	エアコン	新車品のみ O印 を記入																				
外装色 ホワイト	カラーNo. ()	内装色 ()	オプション サンルーフ 革シート																				
左・右 左	輸入 ディーラー	走行 7,510 km	ナビ TV キーレス																				
セールスポイント																							
検査記入欄 書類送付は成約後10日後がかかります。 天張りスレ シートシミ・スレ アウターミラーズ		修復歴 有・無 <table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table> 登録No. 月 日 までに名変できる方 名変中 車検番号 JJ 1-3024313		A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ/ボケ	G	ガラスキズ														
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済														
FW トビ	シミ	ヤブレ	コガ	コガ穴	オーディ穴	シリアル No.	最大積載量 Kg																