


2019 Honda N-VAN G Honda Sensing		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HBD-JJ1	DISPLACEMENT 658 cc		
YEAR / REG. 2019/08	MILEAGE 125,691 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Kei		
CHASSIS NO. JJ1-3023465	DIMENSIONS (L X W X H) 340 × 148 × 195 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Document delivery will take approximately 10 days after contract. Interior dirt, stains, underbody C2.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 / 8月	メーカー ホンダ	ドア枚数 5	ボディ構造 軽四	評価値 3.5																				
車種 N-VAN	グレード G・ホンダセンシング	型式 HBD-JJ1	駆動方式 2WD	内装 A・B・C																				
車検 - / - / -	燃料 ガソリン	変速機 AT	後日送り品 (保証書・取扱説明書等)																					
走行 125,691 km	カラーNo. ホワイト	エアコン ○	新車品のみ ○印 を記入																					
外装色 ()	内装色 ()	標準定員 人	サンルーフ ○	革シート ○																				
ハンド 左・右	輸入 ディーラー	7,510円	ナビ ○	TV ○																				
セールスポイント																								
検査記入欄		修復歴 有・無																						
書類送付は成約後10日前後がかかります。		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコミ/サレ</td><td>B</td><td>キズ・ヘコミ</td><td>P</td><td>色あせ・ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>			A	キズ	U	ヘコミ/サレ	B	キズ・ヘコミ	P	色あせ・ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコミ/サレ	B	キズ・ヘコミ	P	色あせ・ボケ	G	ガラスキズ															
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済															
室内汚れ、シミ		登録No. 月 日 までに名義できる方																						
下回りC2		車検番号 JJ 1-3023465																						
FW	トビ	ワレ	外装	小																				
内装	シミ	ヤブレ	コガ	コガ穴																				