

2019 Honda N-VAN Plus Style Fun Honda Sensing		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HBD-JJ1	DISPLACEMENT 658 cc		
YEAR / REG. 2019/09	MILEAGE 42,849 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Kei		
CHASSIS NO. JJ1-3030328	DIMENSIONS (L X W X H) 340 × 148 × 195 cm		
SALES POINTS			
Pre-Collision Braking Navigation System		Adaptive Cruise Control	
INSPECTOR REPORT			
Exterior has minor scratches (A), minor dents (U), and light line scratches. Front windshield has partial stone chips. Interior shows scuffs, scratches, wrinkles, and dirt. Scratches on the lower front. A few minor dents (AU) on the roof.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 / 9月	メーカー ホンダ	ドア数 5	ボディ形状 軽四	評価点 4.5					
車名 N-VAN + スタイル	グレード ファン・ホンダセンシング	駆動方式 2WD	4WD						
車種 自家用・その他 ()	排気量 660 cc	型式 HBD-JJ1	通称 A・B・C	内装 A・B・C					
年 9	月 9	抹消 イオン	ディーゼル	後日送り品 ()					
走行 42,849 km	インパネ	CVT							
外装色 シャイニンググレーメタリック	カラーNo. NH880M	エアコン AC・AG・WAG・ ()	装備品のみ O印 を記入						
()	内装色 ()	定員 4人	AW	サンルーフ					
左・右 ()	輸入 ()	走行 ()	7,510円	()					
セールスポイント									
ホンダセンシング ギャザズナビ フルセグTV ナビ連動ドラレコ ETC LEDヘッドランプ&フォグランプオートライト アダプティブクルーズ ステアリングスイッチ 車速連動オートロック USB									
検査記入欄									
外装A・U、ウス線キズ フロントガラス飛石部分的内装スレ・キズ・しわ・汚れ フロント下スリキズ ルーフAU小範囲									
修復歴									
有 ()									
A	キズ	U	ヘビキズ	B	キズヘビキズ	D	キズヘビキズ	G	ガラスキズ
W	軽微キズ	S	サビ	C	腐食	X	交換済	XX	交換済
登録No.					名義中				
月					日				
車体番号					JJ1-3030328				
FW	()	輸入	フレ	外装	小	ボディ	エアロ	シフト	No.
内装	()	シス	ヤブレ	コダ	コダ穴	オーディオ	()	重量	kg