

2019 LandRover RANGEROVER Evoque S		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3DA-LZ2NA	1,999 cc		
YEAR / REG.	MILEAGE		
2019/09	50,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Other	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
SALZA2AN8LH032008	438 × 191 × 165 cm		
SALES POINTS			
Alloy Wheels		Leather Seats	
Power Seats (Front)		Pre-Collision Braking	
Cruise Control		Front Camera	
Side Camera		Back Camera	
360° Camera		Navigation System	
Sound System (180W, 6 Speakers)			
INSPECTOR REPORT			
Exterior: Minor scratches and dents have been repaired, but some small scratches and dents remain. Interior: Some stains and dirt are partially present. Accident History: No abnormalities in the frame.			

[illegible]