

2019 SUBARU Levorg 1.6 GT EyeSight		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-VM4	DISPLACEMENT 1,599 cc		
YEAR / REG. 2019/07	MILEAGE 125,343 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Station Wagon		
CHASSIS NO. VM4-142245	DIMENSIONS (L X W X H) 469 × 178 × 149 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control		Leather Seats Cruise Control	
INSPECTOR REPORT			
Removed equipment: Tire pressure sensor. Trim A. Seat wrinkles/wear. Steering wheel wear/peeling. Body minor wear (A).			

新車登録済		メーカー スバル		ドア数 5		ボディ形状 ステーションワゴン		評価点 特価点	
R1 / 7月		車名 レヴォーグ		グレード 1.6GTアイサ イト		駆動方式 2WD ④D		3.5	
車種 自家用・その他()		諸費用 1590 CC		型式 DBA-VM4		通称型 		内装 A・C・D	
乗換 [] 8年 [] 7月 / 扶消		総走行 km ハイブリッド ()		ディーゼル ()		後日送り品 () ※・取扱説明書等 ()			
走行 口内にマーク付人物入(※・全席)・盗(※・全席) [] 1 [] 2 [] 5 [] 3 [] 4 [] 3		シフト AT							
外装色 ブラック (カラーNo. D4S)		エンジン AG・WG・WAG・()		装備品のみの印を記入					
() (内装色) ブラック		重量目安 5人		PS () サルーフ ()					
シロ左・右 輸入区分 ディーラー・運行		ガラス割れ料 13,610円・保証額		エアバック ABS ナビ TV キーレス					
セールスポイント				※写真					
BSM									
ACC									
パドルシフト付ステアリング									
検査記入欄				修復歴 有 ()					
取外装備：空気圧センサー				A キズ U ヘルスヤリ B キズヘコ P 熱変色・割け Q ギヤノ		W 補修跡 R サビ C 腐食 X 交換部 YX 交換部			
トリムA シートシワスレ ハンドルスレハゲ				登録地		月 日		名義	
ボディウサ				車体番号 VM4-142245		どこに名義できる			
PW ()	燃A	フレ	外装 小 () ()	ホイール () ()	エアロ A・ウレ	シリアク 本類	高3	備	高3
内装 ()	シミ	ヤブレ	コガ	コガス	オーデカス ()	高3	備	高3	最大積載量