

2019 Lexus IS IS300 F Sport		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-ASE30	1,998 cc		
YEAR / REG.	MILEAGE		
2019/07	68,346 km		
DOORS	SEATS		
4	5		
DRIVETRAIN	TRANSMISSION		
2WD (FR)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	Sedan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
ASE30-0006251	468 × 181 × 143 cm		
SALES POINTS			
Alloy Wheels		Leather Seats	
Power Seats (Front)		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
Navigation System		Lexus IS Premium Sound System (10 s...	
INSPECTOR REPORT			

年式登録		メーカー		ドア数		ボディ形状		評価点				
R1 / 7月		レクサス		4		セダン						
		IS		グレード		IS300FS ポーツ		駆動方式 2WD 4WD				
		1990 CC		型式		DBA-A5E30		内装				
車種		自家用・その他()		国産車		輸入車		A (B) C				
車検		- - - 年 / - 月 / - 日		鑑別		ディーゼル		後付選り込み (保証書・取扱説明書等)				
走行		C区にマーク記入(Aも可)※ 点火系、油圧系、電装系		シフト		オートマチック						
外観色		パール		カラーNo.		AC - AG - WAG - ()						
()		色番号は1桁以内 (色分けと記入)		内装色		標準塗装		5人				
シート		左・(裏) 右・(表)		輸入区分		ディーラー・並行		リース				
		価格		円		消費税		円				
		11,900		円		消費税		円				
セルスポイント												
ユーザー買取・雷克萨斯セーフティシステム+・モデルスタエアロパーツ・純正メーカナビ・フルセグTV・ブラインドスポットモニター・クリアランスソナー・ETC・LEDヘッドライト・ハーフレザーシート・シートヒーター・社外マフラー												
検査記入欄												
修復歴 有 (無)												
A	キズ	N	キズ	I	H24オヤレ	B	キズ	H23O	P	黄色サビ割れ	G	ガラスキズ
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済			
名義中												
月 日 までに名義であること												
車体番号 ASE30-0006251												
全長 468 cm 全幅 181 cm 全高 143 cm 最大積載量												