

2019 Lexus NX 2.0 NX300		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-AGZ10	1,998 cc		
YEAR / REG.	MILEAGE		
2019/11	32,230 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
AGZ10-1024727	464 × 184 × 164 cm		
SALES POINTS			
Alloy Wheels		Power Tailgate	
Power Seats (Front)		Pre-Collision Braking	
Adaptive Cruise Control		Side Camera	
Back Camera		Navigation System	
Lexus NX Premium Sound System (10 s...			
INSPECTOR REPORT			
Exterior has faint line scratches. Shift knob has scuff scratches. Interior trim has scratches. Interior has pet hair. Steering wheel shows scuff/wear. Front glass has scratches, stone chips, cracks, repair marks, and requires replacement. Interior has scratches, dirt, burns, holes, scuffs, tears, and rips.			

初登録年月 令和 11 月	車名・グレード NX NX300	評価点 (4.5)	2WD 4WD 2WD
ディーラー・並行 モデル年式 年 ハンドル 左・右	型式 DBA-AGZ10	排気量 2000	ドア 形状 5 HB
		定員 積載 5人 kg	外装 内装 A B

車種 家用	シフト FAT	セールスポイント (正常に機能するものに限ります) キーレススマートキー・ETC ナビ・フルセグ・全方向カメラ
車検 年 月 (日) 走行 3万 2千 230 km 色 ブラック	燃費 AAC 燃料 ガソリン	
R券 12,370 円		

注意事項申告欄 外装 うすい傷キズ 外装 小A・小U シフトノブスレキズ 内張り キズ 室内 ベットの毛 ハンドル すれ	新車保証書 有・ 無
--	--------------------------

フロントガラス 内装 (キズ) 飛石 ヒビ割・リペア跡・X要 (キズ) 汚レ・コゲ・穴・ズレ キレ・破レ	車台番号 1024727
---	---

登録番号 1024727	車検 年 月 (日) 走行 3万 2千 230 km
---	---