

2019 MAZDA Carol 5D GL		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HB36S	DISPLACEMENT 658 cc		
YEAR / REG. 2019/09	MILEAGE 30,669 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Silver		
BODY TYPE Kei			
CHASSIS NO. HB36S-233229	DIMENSIONS (L X W X H) 340 × 148 × 148 cm		
INSPECTOR REPORT			
Exterior: Minor scratches and dents have been repaired, but some small ones remain. Interior: Some noticeable dirt and stains are present. No abnormalities in the frame components.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 R1/9月	メーカー マツダ	ドア数 5	ボディ形状 軽四	評価点 4
車名 キャロル	グレード GL			
車種 自家用	型式 HB36S	排気量 660	燃料 ガソリン	内装 B
車検 -年-月/月	走行 30,669 km	駆動 前	エアコン AC	最大積載量 Kg
外装色 シルキールパーメタリック	カラーNo. ()	リサイクル料 15,000円	販売番号 HB36S-233229	
()	シフト フロア	AT	乗車定員 4人	長さ cm
後日送り品 (保証書・取扱説明書等)	グー鑑定 品質検査報告書 輸入車認定証 日本自動車流通協会			
装備 ① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿	グー鑑定 コンディションチェックシート K32126C2101			
セルスポイント	確定日 2025年3月21日 再確定日			
CD/横滑り防止装置(ESC)運転席エアバック/運転防止システム/キーズエントリー/ABS/助手席エアバック/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/シートヒーター	車両状態の説明			
査定員記入欄	小 カードサイズ未満 中 A4サイズ未満 大 A4サイズ以上 数値 金額以上			
※ダメージレベルに関する注意事項 傷は記号のみ 小は1 中は2 大は3 さす 傷小 ⇒ A へこみ 小 ⇒ U1 さす 傷 ⇒ A2 さす へこみ 大 ⇒ A3	車両状態の図解			
F W トリコ ① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿	車両状態の図解			
内装 ① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺ ㊻ ㊼ ㊽ ㊾ ㊿	車両状態の図解			
クオリティグレード説明 外装: 気になるキズやヘコミは補修済みですが、小さなキズやヘコミが残っています。 内装: 気になる汚れ等が、部分的にあります。 修復歴: 骨格部位に異常はありません。	車両状態の図解			