

2019 MAZDA Carol 5D GS		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HB36S	DISPLACEMENT 658 cc		
YEAR / REG. 2019/04	MILEAGE 37,000 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Silver		
BODY TYPE Kei			
CHASSIS NO. HB36S-231544	DIMENSIONS (L X W X H) 340 × 148 × 148 cm		
SALES POINTS			
Pre-Collision Braking		Navigation System	
INSPECTOR REPORT			
Interior has scratches and dirt. Seats show scuffs and wrinkles. Exterior has minor and light scratches. Vehicle was purchased with an AA rating of 4 points.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 H31/4月	メーカー マツダ 車名 キャロル	ドア枚数 5	ボディ形状 軽四	評価点 4
車種 自家用・その他 ()	排気量 660 CC	型式 HB36S	内装 A・B・C	
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	走行 37,000 km	走行 37,000 km
走行 37,000 km	インパネ	AT		
外装色 シルキーシルバームエタリック	カラーNo. 000	エンジン Qd・AAG・WAG・()	装備品のみ ORP を記入	
内装色 ()	乗車定員 4人	PS	AW	サンルーフ
左・右 左・右	ディーラー・並行	7,930円	エブリック	TV
セールスポイント CD/横滑り防止装置 (ESC) / HID・キセノン・ディスプレイ/運転席エアバック/盗難防止システム/キーレスエントリー/ABS/助手席エアバック/メモリーナビ他/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/シートヒーター				
検査記入欄 内装キズ、汚れ シートスレ、シワ 外装キズ、薄キズ AA評価4点仕入れ				
車検 A キズ U ヘッドライト B キズ・ヘッド C 色あせ・ボケ D ガラスキズ W 補修跡 S サイズ C 腐食 X 交換済 XX 交換済 登録No. 月 日 までにも名義できる方 車体番号 HB36S-231544 シリアル No. FW トヨタ 備A フレ 外装 小 A・B・C エアロ 内装 300 シス ヤブレ コガ コガス オーディオ A・B・C				
車検 長さ 幅 高さ 最大積載量 cm cm cm Kg				