2019 MAZDA CX-3 XD

OVERALL	EXTERIOR	INTERIOR
4.5	-	-

MODEL CODE 3DA-DK8FW	DISPLACEMENT 1,756 cc
YEAR / REG. 2019/07	MILEAGE 72,000 km
DOORS 5	SEATS 5
DRIVETRAIN 2WD (FF)	TRANSMISSION AT
FUEL Diesel	STEERING Right
EXTERIOR COLOR Gray	BODY TYPE SUV
CHASSIS NO. DK8FW-104883	DIMENSIONS (L X W X H) 428 × 177 × 155 cm

SALES POINTS

Alloy Wheels
Back Camera
Pre-Collision Braking
Navigation System

INSPECTOR REPORT

Moderate seat wear. Various minor scratches and small dents.

ORIGINAL JAPANESE AUCTION SHEET



初年度登録 R1 / 7月
メーカー マツダ
ドア枚数 5
ボディ形状 SUV/クロカン
評価点 4.5
車名 CX-3
グレード XD
駆動区分 2WD 4WD
車歴 自家用 ・ その他 ( )
排気量 1800 cc
型式 3DA-DK8FW
通称型式
内装 A ・ B ・ C
車検 - - 年 月 / 抹消
燃料 ガソリン ディーゼル ハイブリッド ( )
後日渡り品 (保証書 ・ 取扱説明書 等)
走行 7,000 マイル KM
シフト フロア AT
外装色 グレー
カラーNo. (47A)
エアコン AC ・ ACC ・ WAC ・ ( )
装備品のみ ○印 を記入
( ) 色変更は()内に「色変」と記入
内装色
乗車定員 5 人
PS PW AW サンルーフ 革シート
ハンドル 左 ・ 右
輸入区分 ディーラー ・ 並行
リサイクル料 10,830円 ・ 預託無
エアバック ABS ナビ TV キーレス

セールスポイント

純正ナビ バックカメラ コーナーセンサー BSM LEDヘッドライト レーンキープ 電動パーキングブレーキ ETC 純正18インチアルミ プッシュスタート スマートキー Bluetooth

修復歴
有 ・ 無

検査記入欄

シートスレ中
各小キズ小凹

A	キズ	U	ヘコミ・オサレ	B	キズ・ヘコミ	P	色あせ・ボケ	G	ガラスキズ
W	補修跡	S	サビ	C	腐食	X	交換車	XX	交換済

登録No. 名変中
月 日 までに名変できる方
車体番号 DK8FW-104883
シリアルNo.

FW	トビ石	傷A	ワレ	外装	小 A・U	ホイル A・曲	エアロ A・ワレ
内装	ヨゴレ	シミ	ヤブレ	コゲ	コゲ穴	オーディオ穴	スレ

車輌 長さ cm 幅 cm 高さ cm 最大積載量 Kg