

2019 MAZDA CX-30 20S L Package		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
5BA-DMEP	1,997 cc		
YEAR / REG.	MILEAGE		
2019/10	47,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
DMEP-101508	440 × 180 × 154 cm		
SALES POINTS			
Alloy Wheels		Power Tailgate	
Leather Seats (Perforated Leather)		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
360° Camera		Mazda Harmonic Acoustics (8 speakers)	
Navigation System			
INSPECTOR REPORT			
Exterior: Minor scratches and dents have been repaired, but some small ones remain. Interior: Some noticeable stains and dirt are present in parts. Repair History: No abnormalities in the frame/structural components.			