2019 MAZDA CX-30 20S L Package

OVERALL	EXTERIOR	INTERIOR
4	-	-

MODEL CODE 5BA-DMEP	DISPLACEMENT 1,997 cc
YEAR / REG. 2019/11	MILEAGE 59,600 km
DOORS 5	SEATS 5
DRIVETRAIN 2WD (FF)	TRANSMISSION AT
FUEL Petrol	STEERING Right
EXTERIOR COLOR Blue	BODY TYPE SUV
CHASSIS NO. DMEP-102246	DIMENSIONS (L X W X H) 440 × 180 × 154 cm

SALES POINTS

- **Alloy Wheels**
- **Power Tailgate**
- **Adaptive Cruise Control**
- **Navigation System**
- **Leather Seats (Perforated Leather)**
- **Pre-Collision Braking**
- **Back Camera**
- **Mazda Harmonic Acoustics (8 speakers)**

INSPECTOR REPORT

Exterior: Minor scratches and dents have been repaired, but some small ones remain. Interior: Some noticeable stains are present in parts. Accident History: No abnormalities in the frame.

ORIGINAL JAPANESE AUCTION SHEET



青枠内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 R1/11月	メーカー マツダ	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 4
	車名 ＣＸ-３０	グレード ２０Ｓ Ｌパッケージ		
車検 自家用	修復歴	ハンドル 右	型式 5BA-DMEP	排気量 2000
燃料 ガソリン	内装 C			
車検 8年11月/抹消	走行 (□内にマークを記入（※：交換 ★：修復 #：不明）) 59,600 km	駆動 2WD	ミッション AC	乗車定員 Kg
外装色 ポリメタルグレーメタリック	カラーNo. ( )	リサイクル料 9,720円・預託無	車台番号 DMEP-102246	
( ) 位置単位は（）内に「色番」を記入	内装色	シフト フロア６ AT	乗車定員 5 人	長さ cm 幅 cm 高さ cm

後日送り品（ 保証書 ・ 取扱説明書 等 ）

装備

セールスポイント

査定員記入欄

※ダメージレベルに関する注意事項

クオリティグレード説明

外装:気になるキズやヘコミは補修済みですが、小さなキズやヘコミが残っています。

内装:気になる汚れ等が、部分的にあります。

修復歴:骨格部位に異常はありません。

グー鑑定 コンディションチェックシート K324266G0213

鑑定日	2026年7月2日		再鑑定日				
クオリティーグレード	外装	★★★★	内装	★★★★	修復歴	修復歴 無	種類 正常

車両状態の説明

小	カードサイズ未満	中	A4サイズ未満	大	A4サイズ以上	数量	2個以上

車両状態の確認は、停止状態で実施できる範囲で行っています。