


2019 Mazda CX-30 20S Proactive Touring Selection		OVERALL		4.5
		EXTERIOR	INTERIOR	
		-		
MODEL CODE		DISPLACEMENT		
5BA-DMEP		1,997 cc		
YEAR / REG.		MILEAGE		
2019/10		85,000 km		
DOORS		SEATS		
5		5		
DRIVETRAIN		TRANSMISSION		
2WD (FF)		MT		
FUEL		STEERING		
Petrol		Right		
EXTERIOR COLOR		BODY TYPE		
Silver		Hatchback		
CHASSIS NO.		DIMENSIONS (L X W X H)		
WDD2052422F095395		439 × 179 × 154 cm		
SALES POINTS				
Alloy Wheels		Power Tailgate		
Pre-Collision Braking		Adaptive Cruise Control		
Back Camera		Navigation System		
Mazda Harmonic Acoustics (8 speakers)				
INSPECTOR REPORT				
Multiple scratches on the left rear door. Driver's seat has wrinkles, and the steering wheel has scuffs. Please note that issues related to preventative maintenance (e.g., consumables) are not covered.				

ORIGINAL JAPANESE AUCTION SHEET

車種 R1 10月	メーカー マツダ	ドア数 5	ボディ形状 コンパクト/ハッチバック	評価点 4.5
車名 CX-30	グレード 20S プロアクティブ ツーリングセレクション	駆動方式 4WD	年式 2019	登録区分 A・C
車体 白車用・その他()	排気量 1990 cc	型式 5BA-DMEP	燃料 ガソリン	内装 A・C
走行 85,000 km	エンジン 2.0L	変速機 MT	後付部品 (保証書・取扱説明書等)	
外装色 マシングレブプレミアムメタリック	カラーNo. ()	エアコン ()	新着品のみ・O印を記入	
内装色 ()	車庫 ()	PS ()	PW ()	AW ()
左・右 ()	ディーラー ()	ABS ()	サンルーフ ()	シート ()
セールスポイント				
検査記入欄	修復歴 有・無			
左リアドアに複数の先傷	A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損			
0シートシワ、ステアリングスレ	名義中			
本車両に対する予防整備(消耗品等)の不具合、劣化等に関しましては免責事項となります。	月 日 まで名義で受取る			
	WDD2052422F095395			
内装 ()	シロ ()	サブリ ()	コグス ()	オーディオ ()
長さ 439 cm	幅 179 cm	高さ 154 cm	最大積載量 kg	