

2019 MAZDA CX-30 4WD XD L Package		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
3DA-DM8P	1,756 cc		
YEAR / REG.	MILEAGE		
2019/09	34,900 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Gray	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
DM8P-100149	440 × 180 × 154 cm		
SALES POINTS			
Alloy Wheels		Leather Seats (Perforated Leather)	
Power Tailgate		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
360° Camera		Navigation System	
Mazda Harmonic Acoustics (8 speakers)			
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 R1 / 9月	メーカー マツダ	ドア数 5	ボディ形状 SUV/クロカン	評価点 4.5
車名 CX-30	グレード 4WD XD_Lパッ ケージ	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 1800	型式 3DA-DM8P	登録区分 A・⑤・C	
年式 8年9月	燃料 ガソリン	変速機 AT	後付選用品 (保証書・取扱説明書等)	
走行 34,900マイル	カラーNo. ボリメタルグレーメタリック	エンジン Qd・AAG・WAG・ ()	新車品のみ・O印を記入	
外装色 ()	内装色 ()	乗車定員 5人	新車品のみ・O印を記入	
左・ ()	右・ ()	9,720円	エレクトロニクス・TV・その他	
セールスポイント				
BOSE純正ナビ/衝突安全装置/シートヒーター/車線逸脱 防止支援システム/シートフルレザー/電動バックドア/ハ ッドランプ LED/ETC/BD付ABS/横滑り防止装置				
修復歴 有・⑥				
検査記入欄				
A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損				
名義中				
月 日 まで名義中				
DM8P-100149				
車種 SUV				
ボディ形状 SUV/クロカン				
駆動区分 2WD 4WD				
変速機 AT				
乗車定員 5人				
9,720円				