

| 2019 MAZDA CX-5 XD L Package                                                                                                                                                                                                                                 |                        | OVERALL                 |          |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|-------------------------|----------|
|                                                                                                                                                                                                                                                              |                        | EXTERIOR                | INTERIOR |
|                                                                                                                                                                                                                                                              |                        | -                       | -        |
| MODEL CODE                                                                                                                                                                                                                                                   | DISPLACEMENT           |                         |          |
| KF2P                                                                                                                                                                                                                                                         | 2,188 cc               |                         |          |
| YEAR / REG.                                                                                                                                                                                                                                                  | MILEAGE                |                         |          |
| 2019/05                                                                                                                                                                                                                                                      | 26,682 km              |                         |          |
| DOORS                                                                                                                                                                                                                                                        | SEATS                  |                         |          |
| 5                                                                                                                                                                                                                                                            | 5                      |                         |          |
| TRANSMISSION                                                                                                                                                                                                                                                 | FUEL                   |                         |          |
| AT                                                                                                                                                                                                                                                           | Diesel                 |                         |          |
| STEERING                                                                                                                                                                                                                                                     | EXTERIOR COLOR         |                         |          |
| Right                                                                                                                                                                                                                                                        | Other                  |                         |          |
| BODY TYPE                                                                                                                                                                                                                                                    |                        |                         |          |
| SUV                                                                                                                                                                                                                                                          |                        |                         |          |
| CHASSIS NO.                                                                                                                                                                                                                                                  | DIMENSIONS (L X W X H) |                         |          |
| KF2P-317122                                                                                                                                                                                                                                                  | 455 × 184 × 169 cm     |                         |          |
| SALES POINTS                                                                                                                                                                                                                                                 |                        |                         |          |
| Alloy Wheels                                                                                                                                                                                                                                                 |                        | Power Tailgate          |          |
| Power Seats (Front)                                                                                                                                                                                                                                          |                        | Leather Seats (Leather) |          |
| Pre-Collision Braking                                                                                                                                                                                                                                        |                        | Adaptive Cruise Control |          |
| Side Camera                                                                                                                                                                                                                                                  |                        | Back Camera             |          |
| 360° Camera                                                                                                                                                                                                                                                  |                        | Navigation System       |          |
| INSPECTOR REPORT                                                                                                                                                                                                                                             |                        |                         |          |
| Exterior: If there were noticeable scratches or dents, they have been neatly repaired, but small scratches and dents may still remain. Interior: There are some noticeable stains, but only in certain areas. Repair history: No abnormalities in the frame. |                        |                         |          |

[illegible]