

2019 Mazda CX-5 XD Proactive		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE 3DA-KF2P	DISPLACEMENT 2,188 cc		
YEAR / REG. 2019/03	MILEAGE 80,435 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE SUV		
CHASSIS NO. KF2P-315008	DIMENSIONS (L X W X H) 455 × 184 × 169 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Adaptive Cruise Control Back Camera		Leather Seats Pre-Collision Braking Side Camera	
INSPECTOR REPORT			
Equipment change: Current wheels/tires replaced with genuine wheels and summer tires. Steering wheel has scuffs. Seats have wrinkles and scuffs. Front passenger door rubs against the front fender when opening (still functional). Minor scratch on door mirror. Undercarriage has rust. Minor scratch on door edge.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H31 / 3月	メーカー マツダ	ドア数 5	ボディ形状 SUV/クロカン	評価点 3.5
車種 自家用・その他 ()	型式 2180 CC 3DA-KF2P	グレード XD プロアクティ	駆動方式 4WD	内装 A・⑤・C
車検 10年3月 / 扶養 80,435マイル	燃料 ガソリン	変速機 AT	装備選り込み (保証書・取扱説明書等)	
外装色 グレー	カラーNo. 0	エアコン AG・⑤・WAG・()	装備品のみ・O印を記入	
内装色 ブラック	乗車定員 5人	PS ⑤	サンルーフ ⑤	キーレス ⑤
走行 左・()	ディーラー・直付	12,340円	ABS ⑤	ナビ ⑤
セールスポイント				
HUD				
検査記入欄		修復歴 有・⑥		
入替装備 両替タイヤホイール→純正ホイール、サマータイヤ替 ハンドルスレ シートシワ、スレ 両手側ドア開閉時、フロントフェンダーと干渉有り(開閉可能) ドアミラー-A 下回りS ドアエッジA		A キズ B U ヘコみサレ B キズヘコみ P 色あせ・サレ Q ガラスキズ W 腐蝕跡 S サビ C 腐食 X 交換車 XX 交換車 修理月 月 日 名変中 車検月 月 日 まで名変できる方 車検番号 KF2P-315008		
内装 ⑤	シロ ⑤	サブレ ⑤	コグ ⑤	コグス ⑤
オイル ⑤	エアロ ⑤	シフト ⑤	ブレーキ ⑤	タイヤ ⑤
重量 cm	重量 cm	重量 cm	重量 cm	重量 0 kg