


2019 MAZDA CX-8 XD L Package		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE KG2P	DISPLACEMENT 2,188 cc		
YEAR / REG. 2019/09	MILEAGE 81,377 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. KG2P-211655	DIMENSIONS (L X W X H) 490 × 184 × 173 cm		
SALES POINTS			
Alloy Wheels Leather Seats (Nappa Leather) Power Seats (Front) Adaptive Cruise Control Side Camera 360° Camera		Roof Rails Power Tailgate Pre-Collision Braking Front Camera Back Camera Navigation System	
INSPECTOR REPORT			

年式登録	メーカー	車種	型式	ボディカラー	グレード	SUV/クワカン	駆動方式
R1 / 9月	マツダ	C X-8	シブ ジ	L パッケージ	エンジン	4WD	9.0
車検	自乗用・その他 ()	排気量	2200 CC	形式	KG2P	燃費	A・B・C
車検	- - 年	月	日	燃料	ガソリン	オイル	後日送付品 ()
走行	(口)にマーキング記入(※全席 ※他正記 ※左側)	キロ	81,377	シフト	フロア 6 AT	新着品のみ O印 を記入	
外装色	ブラック (41W)	カラー名	Qe・AAG・WAG・()	内装色	7人	サンルーフ	シート
ドア	左・右・開入部分	ディーラー	走行距離	3,480 km	オプション	ナビ	スペア
セルポイント	パノラミックビューモニター / ハーフレザーシート / OP9インチディスプレイ / ブラインドスポットモニター / スペアタイヤ / シートヒーター / パワーシート / ETC / LEDヘッドライト / パワーバックドア / ワンオーナー /						
検査記入欄							
内外装小傷							
FW	トボ石	傷A	ウレ	汚損	小	キズ	エアロ
内装	ヨゴレ	シミ	ヤブレ	コガサ	オデカ	汚れ	スレ



A	キズ	U	へこみ・オサレ	B	キズ・へこみ	P	色あせ・汚れ	G	ガラス・スチ
W	破損部	S	サビ	C	腐食	X	交換面	XX	交換済

登録No.	福山	332	も	8739	名実町
	月 日 までにご覧できる方				

PW	トピ石	傷A	ワレ	外装	ホイル A・U	ホイル A・曲	エアロ A・ワレ	シリアル No.				
内装	ヨゴレ	シミ	ヤブレ	コゲ	コゲ穴	オーディオ穴	スレ	車庫	長さ cm	幅 cm	高さ cm	最大積載量