

2019 Mazda Demio 15S Proactive S Package Collision Mitigation Brake		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DJLFS	DISPLACEMENT 1,496 cc		
YEAR / REG. 2019/01	MILEAGE 15,423 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Hatchback		
CHASSIS NO. DJLFS-706875	DIMENSIONS (L X W X H) 406 × 170 × 153 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Back Camera		360° Camera	
Navigation System			
INSPECTOR REPORT			
Exterior: Notable scratches and dents have been repaired, but minor ones remain. Interior: The cabin is clean with no noticeable stains. Repair history: Signs of impact near the front or rear ends of the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグレー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H31/1月	メーカー マツダ	ドア枚数 5	ボディ形状 コンパクトハッチバック	評価点 R
車名 MAZDA 2	グレード 15Sプロアクティブ Sパッケージ☆衝突被害軽減ブレーキ☆	排気量 1500	燃料 ガソリン	内装 A
車種 自家用	右 DJLFS	走行距離 15,423 km	年式 H31	重量 AAC
年式 15年	走行 15,423 km	車検 H31	重量 AAC	重量 Kg
先主 ソニックシルバースタリク	カラーNo. ()	リサイクル料 8,140円	車検番号 DJLFS-706875	
内装 ()	シフト フロア 6 AT	乗車定員 5人	長さ cm	幅 cm

※車両の取扱い、および修理・改造等に関する事項については、別途記載の注意事項を必ずご確認ください。

グレー鑑定 自動車検査所
検査員 佐藤 健一
検査日 2020年06月22日

車検状況の図解

車検状況の図解は、停止状態で撮影した写真に基づいて作成されています。走行時には必ず安全運転をお願いします。

車検状況の図解は、停止状態で撮影した写真に基づいて作成されています。走行時には必ず安全運転をお願いします。