

2019 MAZDA FLAIR WAGON Flair Wagon Custom Style 660 Hybrid XT		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-MM53S	DISPLACEMENT 658 cc		
YEAR / REG. 2019/06	MILEAGE 41,616 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Kei		
CHASSIS NO. MM53S-823168	DIMENSIONS (L X W X H) 339 × 147 × 178 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Navigation System		Power Sliding Doors (Both Sides) (Both... Cruise Control	
INSPECTOR REPORT			
Exterior: Small A, Small U, front bumper misalignment. Interior: Room scratches, headliner stains. Front glass: Scratches, stone chips, cracks, repair marks, replacement required. Interior: Scratches, stains, burns, holes, scuffs, tears, rips.			

初度登録年月 令和1 6月	車名・グレード フレアワゴンカスタムスタイル ハイブリッドXT	評価点 (2WD) (4WD)	評価点 (4.5)		
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DAA-MM53S	排気量 660 CC	ドア 5	定員 4人	外装 内装 B B
車種 自家用		シフト CAT		セールスポイント (正常に機能するものに限りです) スマートキー・ETC・パワースライドドア (両側) サロビ・フルセグTV・スマートキー	
年 月 (日) 走行 4万1千616 km		冷暖房 AAC		燃料 ガソリン	
色 ブラック		色コード ZJ3/C04		装備品 (純正品に限り○をつけてください) (PS) (PW) (ABS) (ESP) (AW)	
R券 9,770 円		前車保証書 有・無		後日誌	
注意事項申告欄 外装 小A・小U Ftoバンパーズレ ルームキズ 天張り 汚れ					
フロントガラス 内装 キズ・傷レ・ヒビ割・リペア跡・X要 キズ・傷レ・コゲ・穴・スレ・キレ・破レ					
車台番号 823168		車台番号 18705			
登録番号 339		登録番号 0018			