

2019 MAZDA Mazda3 Fastback 1.5 15S Touring		OVERALL 5	
		EXTERIOR -	INTERIOR -
MODEL CODE 6BA-BP5P	DISPLACEMENT 1,496 cc		
YEAR / REG. 2019/12	MILEAGE 13,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Hatchback		
CHASSIS NO. BP5P-107726	DIMENSIONS (L X W X H) 446 × 180 × 144 cm		
SALES POINTS			
Alloy Wheels Navigation System		Adaptive Cruise Control Mazda Harmonic Acoustics (8 speakers)	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 / 12月	メーカー マツダ	ドア枚数 5	ボディ形状 コンパクトハッチバック	評価点 5
車名 MAZDA3ファストバック	グレード 1.5 15S ツーリング	駆動方式 2WD	4WD	
車種 自家用・その他 ()	排気量 1500 cc	型式 6BA-BP5P	通称 型式	内装 A・⑨・C
年 -	月 -	日 -	燃料 ガソリン	ディーゼル
走行 13,000 km	マイル 0	シフト フロア 6 AT	後日取り込み ()	取付 ()
外装色 パール	カラーNo. ()	エアコン AG・⑧・WAG・()	整備品のみ O印 を記入	
内装色 ()	乗車定員 5 人	③	④	⑤
左・右 左・右	輸入区分 ディーラー・並行	9,490円・税別	⑥	⑦
セールスポイント 衝突軽減ブレーキ、純正SDナビ、フルセグTV、360°モニター、LEDヘッドライト、ETC、DVDビデオ再生可、レーダークルーズコントロール、アイドリングストップ、コーナーセンサー、革調シートカバー、純正18インチアルミ				
検査記入欄		修復歴 有・⑧		
		A キズ U ヘコみ・サレ B キズ・ヘコみ P 色あせ・ボケ Q ガラスキズ		
		W 補修跡 S サビ C 腐食 X 交換品 XX 交換済		
		登録No. 月 日 までに名変できる方		
		名変中		
		車体番号 BP5P-107726		
PW ① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺		シリアル No.		
内装 ① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺		重量 全重 自重 最大積載量 kg		