

2019 Mazda Mazda3 Fastback 15S Touring		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 6BA-BP5P	DISPLACEMENT 1,496 cc		
YEAR / REG. 2019/07	MILEAGE 33,500 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Station Wagon		
CHASSIS NO. 102937	DIMENSIONS (L X W X H) 446 × 180 × 144 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Navigation System		Pre-Collision Braking Back Camera Mazda Harmonic Acoustics (8 speakers)	
INSPECTOR REPORT			
Scratches and dents present			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 / 7月	メーカー マツダ	ドア数 5	ボディ形状 ステーションワゴン	評価点 4.5
車名 MAZDA3ファストバック	グレード 15Sツーリング	駆動方式 4WD	4WD	
車種 自家用・その他 ()	排気量 1500 cc	型式 6BA-BP5P	変換形式	内装 A・B・C
年 10年	月 7月	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)
走行 33,500 km	マイル 50,000	フロア	AT	
外装色 ブラック	カラーNo. 41W	AG・BG・WAG・ ()	車庫	新車品のみ O印 を記入
内装色 ()	乗車定員 5人	シフト	サンルーフ	車シート
左・右 左・右	ディーラー ディーラー	走行 9,490 km	エレクトロニクス	エレクトロニクス
セールスポイント		修復歴		
・メーカーOPナビ ・地デジ対応 ・Rカメラ ・エリアセンサー ・社外AW ・スマートブレーキサポート ・ブラインドスポット ・ヘッドアップディスプレイ		有・無		
検査記入欄		A ネズ U ヘッドランプ B キズ・ヘコ P 色あせ・汚れ Q ガラスキズ		
傷・凹み有		W 腐蝕 S サイズ C 腐食 X 交換部 YX 交換部		
		名 査 中		
		月 日 までに名 査 できる方		
		車体番号 102937		
内装 ゴキ		シリアル No.		
トボ石 傷A		F 腐食 G 曲 A・フレ		
フレ		車庫		
小 G・H		長さ cm		
ホイール G・H		高さ cm		
エアロ A・フレ		最大重量 kg		
コグ				
コグ穴				
オーディオ穴				
スレ				