

2019 MAZDA Mazda3 Fastback 15S Touring		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE BP5P	DISPLACEMENT 1,496 cc		
YEAR / REG. 2019/12	MILEAGE 89,033 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Hatchback		
CHASSIS NO. BP5P-108262	DIMENSIONS (L X W X H) 446 × 180 × 144 cm		
SALES POINTS			
Alloy Wheels 360° Camera Mazda Harmonic Acoustics (8 speakers)		Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Exterior has stains and light scratches. Handle grip is in poor condition. Interior has light dirt. R-Hosement has an issue.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		19179		0001		シリアナンバー		評価点	
R 01		マツダ 3ファストバック		5		グレード		4	
12月		型式 6BA-BP5P		1,500 cc		燃料		A B C	
車検 R 08 12月		車種 自家用		シフト 6MT		冷却 AC		純正装備品 ○をつける	
走行距離 8万9千333km		マイル (交換) (燃費) (不明)		マニアル		純正ナビ		純正TV	
外装色 ディープ クリスタルブルーメタリック		色替無		カラーNo.		純正AW		SR	
車検No. BP5P-108262		登録No.		9,490円税別		TV機器 (社外品含む) ○をつける		エアコン	
定員 5人		重量 31L		モ 5		ナビ機器 (社外品含む) ○をつける		アナログ	
輸入車のみ		モーター		ディーゼル		HDD		DVD	
セーリングポイント		ディーゼル		ハンドル		CD		SD	
禁煙車		純正8.8インチ		7.6インチ		全周防犯カメラ		LEDヘッドライト	
ETC		ETC		ETC		ETC		ETC	

注意事項・不具合箇所

検査員記入欄：検査員「有」の場合は検査箇所・交換箇所を記入

外装シミ、薄い線傷

ハンドルグリップ不良

室内薄汚れ

RホースメントXX

トリアミラー

キズ

ヒビ

ツレ

上側

無

シヤッキ

無