

2019 MAZDA Mazda3 Fastback 15S Touring		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 6BA-BP5P	DISPLACEMENT 1,496 cc		
YEAR / REG. 2019/07	MILEAGE 70,400 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Hatchback		
CHASSIS NO. BP5P-102904	DIMENSIONS (L X W X H) 446 × 180 × 144 cm		
SALES POINTS			
Alloy Wheels Navigation System		Adaptive Cruise Control Mazda Harmonic Acoustics (8 speakers)	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

印字履歴 R1/7	メーカー トヨタ	ドア数 5	ボディ形状 5	評価点 4.5
車名 マツダ3ファストバック	グレード 15Sツーリング	駆動区分 FF	内装 A B C	
車種 自家用・その他 ()	排気量 1500 cc	型式 6BA-BP5P	通称 型式	
車検 年 月 日	抹消 月 日	燃料 ガソリン	後日送り品 (保証書・取扱説明書等)	
走行 70,400 km	シフト F 6	エアコン AAC	★地図SD	
外装色 ブラック (41W)	カラーNo. ()	乗車定員 5人	装備品のみの印を記入	
内装色 ()	リサイクル料 9,490円	登録料 円	PS PW AW サンルーフ 本革シート	
セーリングポイント	左	右	ABS ナビ TV キーレス	
★シグネチャーエアロF・S・R				
★純正ナビ ★フルセグTV				
★LEDヘッド ★バックカメラ				
★HUD・BSM ★ドライブレコーダー				
★純正18インチAW★アドバンストキー				
★TEIN車高調 ★5ZIGENマフラー				
★PIVOTスロットコントローラー				
★AutoExe Sports Steering				
検査記入欄				
	修復歴 有 () 無 ()	スペア		
	A キズ U ヘッド・ガラス B キズ・ヘッド P 色あせ・ボタ G ガラスキズ			
	W 補修跡 S サビ C 腐食 X 交換部 YI 交換部			
	登録No.			名実中
	月 日			までに名実できる方
	車体番号 BP5P-102904			
FR 1ピスト 爆A フレ 外装 (A・U) ホイル A・曲 A・フレ エアロ シリアル No.				
内装 50レ シミ ヤブレ コガ コガ穴 オーディオ穴	長さ cm	幅 cm	高さ cm	最大積載量 Kg