


2019 Mazda Mazda3 Fastback 15S Touring		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 6BA-BP5P	DISPLACEMENT 1,496 cc		
YEAR / REG. 2019/05	MILEAGE 72,900 km		
DOORS 5	SEATS 5		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Blue		
BODY TYPE Hatchback			
CHASSIS NO. BP5P-100135	DIMENSIONS (L X W X H) 446 × 180 × 144 cm		
SALES POINTS			
Alloy Wheels		Pre-Collision Braking	
Adaptive Cruise Control		Back Camera	
Navigation System		Mazda Harmonic Acoustics (8 speakers)	
INSPECTOR REPORT			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 R1 / 5月	メーカー マツダ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4
車名 MAZDA3ファストバック	グレード 155ツーリング	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 1500 cc	型式 6BA-BP5P	選装 型式	内装 A・B・C
車検 10年5月 / 抹消	燃料 ガソリン	ディーゼル ハイブリッド ()	後付選用品 (保証書・取扱説明書 等)	
走行 72,900 km	シフト AT			
外装色 ディープリスタルブルーマイカ	カラーNo. ()	エアコン QW・AAG・WAG・()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5人	サンルーフ 革シート		
左・右 左・右	輸入 ディーラー・並行	リサイクル料 9,490円・販売税	エレクトロニクス	その他
セールスポイント 純正8インチナビ/衝突安全装置/360° ビューモニター/車線逸脱防止支援システム/ドライブレコーダー 社外ハットランプ LED/USBジャック/Bluetooth接続/ETC				
検査記入欄		修復歴 有・無		
外装AU		A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ W 擦傷跡 S ヤビ C 腐食 X 交換部 YX 交換済		
		登録No. 月 日 までに名義である方 車体番号 BP5P-100135 シリアル No.		
FW トンネル フレ 外装 小 ホイル エアロ ①・② ③・④ A・フレ		取崩 長さ cm 幅 cm 高さ cm 最大積載量 Kg		
内装 ⑤・⑥ シェ ヤブレ コゲ コゲ穴 オーディオ穴 ⑦				