

2019 MAZDA Mazda3 Fastback XD L Package		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE BP8P	DISPLACEMENT 1,756 cc		
YEAR / REG. 2019/05	MILEAGE 23,902 km		
DOORS 5	SEATS 5		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Gray		
BODY TYPE Hatchback			
CHASSIS NO. BP8P-100603	DIMENSIONS (L X W X H) 446 × 180 × 144 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control Navigation System		Leather Seats (Perforated Leather) 360° Camera Mazda Harmonic Acoustics (8 speakers)	
INSPECTOR REPORT			
Interior scratches, trim scratches			

ORIGINAL JAPANESE AUCTION SHEET

出品票		車両番号	19180	納期	0001	シリアル番号		評価点	
年	月	日	車名	トランク	グレード	駆動		4.5	
R 01	5		マツダ 3ファストバック	5	1.8XD Lpkg	4WD			
型式	3DA-BP8P	排気量	1,800 cc	燃料	ガソリン	安全	A	C	
車種	年	月	車歴	シフト	AT	冷房	AC	純正装備品	○をつける
走行距離	2	3	895	マイル	○をつける	純正ナビ	SR	純正TV	
外観色	パールメタリック	色無	カラーNo.	内装色		純正AW	エアB	TV機能	○をつける
車台No.	BP8P-100603	名義	無	月	日	ナビ機能	○をつける	ナビ機能	○をつける
登録No.	扶消	リサイクル	9,490円	未納税		HDD	DVD	SD	
定額	5	納税額	446	179	144	DVR	CD		
輸入車のみ	モデル	年式	輸入区分	ディーラー	走行	ハンドル	左	前車保証書	車検取得
セールスポイント 禁煙車 BOSE 純正ナビ フルセグTV 360°カメラ クルコン シートヒーター パワーシート									

注意事項・不具合箇所

検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入

ルーム内キズ

トリムキズ

ドアヒラ

キズ

ヒビ

ウレ

工数

無

ジャッキ

無

