

2019 MAZDA Mazda3 Sedan 1.8 XD Proactive Diesel Turbo		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE 3DA-BP8P	DISPLACEMENT 1,756 cc		
YEAR / REG. 2019/08	MILEAGE 49,000 km		
DOORS 4	SEATS 5		
TRANSMISSION AT	FUEL Diesel		
STEERING Right	EXTERIOR COLOR Gray		
BODY TYPE Sedan			
CHASSIS NO. BP8P-103760	DIMENSIONS (L X W X H) 466 × 180 × 145 cm		
SALES POINTS			
Alloy Wheels Adaptive Cruise Control 360° Camera Mazda Harmonic Acoustics (8 speakers)		Pre-Collision Braking Back Camera Navigation System	
INSPECTOR REPORT			
Front glass: scratches, stone chips, cracks, repair marks (X required). Interior: scratches, dirt, burns, holes, scuffs, tears, rips.			

初度登録年月 令和1 8 月	車名・グレード MAZDA3セダン XDプロアクティブ	(2WD) 4WD	評価点 (4.5)
ディーラー・並行 モデル年式 年 月 ハンドル 左・右	型式 3DA-BP8P	排気量 1800 CC	ドア 定員 4 5人
		形状 SD	積載 kg
		外装 内装 B B	

車種 家用 車検 令和8 年 8 月 () 日 走行 4万8千700 km 色 グレー 色替 フメ	シフト FAT 冷房 AC 燃料 軽油
---	--

R券 9,490 円	セールスポイント (正常に機能するものに限ります) キーレススタートキー・スマートキー 全方位モニター・電動パーキング
-------------------	---

装備品 (純正品に限り○をつけてください)				
PS	PW	ABS	EAB	AW
SR	ナビ	TV	カフ	

注意事項申告欄	新車保証書 有・ 無
---------	--------------------------

フロントガラス 内装	キズ・飛石・ヒビ割・リペア跡・X要 キズ・汚レ・コゲ・穴・スレ・キレ・破レ
---------------	--

車台番号 103760	登録番号 名交中
--------------------	-----------------

A・キズ	E・エグボ	U・凹み	W・補修跡	S・ナビ	C・窓ガラス	XX・交換品
型式指定番号				類別区分番号		
車検証明用				販売用		
品名	種別	数量	単位	品名	種別	数量